



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: August 28, 2006

Supervisor DRH

Mine Name: Allen Claims Project
Operator Name: A and R Leasing LLC

Permit number: S0450032
Inspection Date: 06/06/2006

Inspector(s): Dan Smith
Other Participants: None
Mine Status: INA

Weather: No adverse conditions
affecting site visit.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:
Data base indicates this site has never been inspected.


Directions to Site:
Easy access to site. Access road is on west side of railroad tracks. See map.


Inspection Summary:
No signs of recent activity. Small amount of acreage disturbed.

Conclusions and Recommendations:
Many comments in the database stating that this mine has not been active (1999, 2000 and 2003).
Recommend that the primary inspector review this mine permit.

Inspector's Signature Daniel D. Smith Date: August 28, 2006

ds
cc: Operator
Attachment: Map & Photos





Mine Number: S0450032
Mine Name: Allen Claims Project
Township 08 S Range 05 W Section 24 SLBM

Inspection Date June 06, 2006
Map Produced by DKS

Acres Disturbed	0.29
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0

Total Acres Disturbed	0.29
-----------------------	------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend

All items symbolized in legend may not be appear on map

- | | |
|-----------------|---|
| County Boundary | Township or range Line |
| Access | Township or range line: location doubtful |
| Mine | Section line |
| NonMine | Section line: location doubtful |
| Other | Disturbed |
| Interstate | Regraded |
| US Route | Seeded |
| State Route | Released |
| Primary Route | Excluded |
| Secondary Route | PreExisting |
| Main Dirt Road | Prelaw |
| Unimproved Road | Bond Area |
| Interchange | SITLA Mineral Leases |
| Trail | BLMSaleableMinerals |
| | CommunityPit |
| | SITLA Mineral Ownership |

DOQ imagery date 2004



0 625

Feet
1:7,500 1 inch equals 625 feet
Verify Scale

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.